

SAFE HOME / LEADSAFE CHARLOTTE

CITY OF CHARLOTTE

HOUSING & NEIGHBORHOOD SERVICES

()	BID OPENING CERT		2 10	
Date of Bid Walk: OCTOBE	02	CoroBEN/8, 2010	8 HNS <u>[9</u> -	22
•	Public Body			
Address	PBE Amount	PBE -15%		+15%
3944 BRISTOLDA.	\$35,925.	# 30,536.2	\$ \$39,0	013.75
	Bid Re	Bidder 3	Bidder 4	Bidder 5
3944 BRISTEDR Y	Bidder 1 Bidder 2 Bidder 2 JOSPEN OBION 33,945)	Diudei 4	Diddel 3
		10/18/	. 8	
	Bid Walk A	, •	(0)	
Office located at 600 E. Trade Str. Bids Opened By: Witnessed By:	1011	oids Recorded By: J.N. ate: OCTOBLE	1.MAHON 18, 20/8	Jan Mahon
	responsive bid is recommended to			



SAFE HOME

CITY OF CHARLOTTE

NEIGHBORHOOD & BUSINESS SERVICES

Company Acknowledgement:

The undersigned, having become thoroughly familiar with the terms, conditions, limitations, and provisions of the housing improvement work to be performed at _3944 Bristol Drive to be funded through the City of Charlotte Neighborhood & Business Services, in addition, having fully inspected the site in all particulars, hereby proposes and agrees to fully perform the work within the time stated and in strict accordance with the proposed contract documents including furnishing of any and all labor and materials, and to do all work required to complete said Work in accordance with the advised respective contractual, for the sum of money:

All labor, materials, services and equipment necessary for the completion of the Work shown on the Drawings and in the Specifications:

Thirty three thousand, nine hundred & Forty Dollars (\$33,945)

Written total

Specs Dated: 10-4-18

Number of Pages: 12 (Rehab Only- NO LEAD)

Addenda # 1 Dated:

Number of Pages:

Addenda # 2 Dated:

Number of Pages:

Project Schedule: Minimum Start Date - 4 weeks after Bid Due Date NOVEMBER 19,2018.

Completion Deadline: DECEMBER 21, 2018.

Please Print and Sign:			
Company Name/Firm: Ja	sper Environmental Servic	es, Inc	
Authorized Representative Na	me: Thaddgus Kuzniai		
Signature:	.//	Date:	10.18.2018



Prepared By: City of Charlotte Housing & Neighborhood Services 600 E. Trade Street Charlotte, NC 28202 (704) 336-7600

Property Details

Address:

3944 Bristol Dr.

Charlotte, NC 28208

Owner:

Marnita Bell

Owner Phone:

Home: (704) 492-7079

Response Due: 10/18/2018 2:00 PM

Single Unit Program(s):

Healthy Homes

Tested-NO LEAD Safe Home FY 2017

LeadSafe 2016

Structure Type:

1025

Square Feet:

Year Built: Property Value:

1957 71400

Tax Parcel:

06107110

Census Tract:

Property Zone:

Council District 3

Repairs

Description

Floor

Room

Exterior

1. Ceiling Repair

DEN/OFFICE/STUDY

Exterior

Repair ceiling finish. Patch drywall or plaster holes in ceiling greater than one inch. All others use an adhesive mesh and mud over mesh with the appropriate material. Wet sand and smooth.



250 **Bid Cost:** Quantity **Total Cost**

Ceiling Repair

LAUNDRY / UTILITY

Repair ceiling finish. Patch drywall or plaster holes in ceiling greater than one inch. All others use an adhesive mesh and mud over mesh with the appropriate material. Wet sand and smooth.



Bid Cost:)	<=	150
•	Base	Quantity	Total Cost

		•		P	_	-	. •	~~==	٠.	•
^							•			
3.	Lau	ndry	/Wa	asher	Co	nne	ction	n Box	(

LAUNDRY / UTILITY

Install PVC vent plpe through the roof, laundry connection box with hot and cold hose bibbs, and 20 amp outlet on a separate circuit to service a washing machine.

	Bio	l Cost:		х		=	700
White Land	,		Base		Quantity	То	tal Cost
4 Doorbell System	•			•	GEN REQ		
Install a doorbell system containing	a low voltage transformer, powe	er connectic	on, buzzer a	and froi	nt door butto	n.	
•	Bio	l Cost:		Х		=	400
•	-		Base		Quantity	То	tal Cost
S. Permits Required			, ,		GEN REQ	• • • • •	** ,
The contractor is responsible obtain	ing and paying for all permits re	gulred. Said	d permits s	hall inc	•		pe of work.
							450
	Bio	d Cost:	Base	X	Quantity	To	tal Cost
			Dase		Quantity		itai Gost
·			•				
6 Dumpster After procuring all required permits,						Collect cor	
•	Remove dumpster and repair ar	y evidence		npsters	ing the site.	Collect cor	
After procuring all required permits, debris using dust control methods. F	Remove dumpster and repair ar	y evidence	of the dum	npsters	ging the site, use, Contrac	Collect cor	ul debris
After procuring all required permits, debris using dust control methods. F	Remove dumpster and repair ar	y evidence	of the dum	npsters	ging the site, use, Contrac	Collect cor ctor may ha	ul debris
After procuring all required permits, debris using dust control methods. F away daily using dump trailers.	Remove dumpster and repair ar	y evidence	of the dum	npsters	ging the site, use, Contrac Quantity	Collect cor ctor may ha	ul debris
After procuring all required permits, debris using dust control methods. Faway daily using dump trailers. Portable Toilet	Remove dumpster and repair ar Bio	y evidence d Cost: manent faci	of the dum Base	npsters X	ging the site, use, Contrac Quantity GEN REQ	Collect cor ctor may ha	ul debris
After procuring all required permits, debris using dust control methods. Faway daily using dump trailers. Portable Toilet	Remove dumpster and repair ar Bio	y evidence d Cost: manent faci	of the dum	npsters X	ging the site, use, Contrac Quantity	Collect cor	ul debris
After procuring all required permits, debris using dust control methods. F away dally using dump trailers. Portable Toilet Provide temporary toilet facilities fro	Remove dumpster and repair ar Bio	y evidence d Cost: manent faci	of the dum	npsters X	Quantity Quantity Quantity Quantity	Collect corrector may ha	ul debris 356 stal Cost
After procuring all required permits, debris using dust control methods. Faway daily using dump trailers. Portable Toilet	Remove dumpster and repair ar Bio m job start until approval of per Bio , celling mounted smoke and he	y evidence i Cost: manent faci	Base illities.	XX	Quantity Quantity Quantity Quantity Quantity	Collect cor ctor may ha	ul debris 356 tal Cost 250 tal Cost
After procuring all required permits, debris using dust control methods. If away daily using dump trailers. Portable Toilet Provide temporary toilet facilities fro	Remove dumpster and repair ar Bio m job start until approval of per Bio , celling mounted smoke and he utside of sleeping areas.	y evidence I Cost: manent faci I Cost: at detector	Base illities.	XX	Quantity Quantity Quantity Quantity Quantity	Collect cor ctor may ha	ul debris 356 tal Cost 250 tal Cost
After procuring all required permits, debris using dust control methods. If away daily using dump trailers. Portable Toilet Provide temporary toilet facilities fro	Remove dumpster and repair ar Bio m job start until approval of per Bio , celling mounted smoke and he utside of sleeping areas.	y evidence i Cost: manent faci	Base illities.	XX	Quantity Quantity Quantity Quantity Quantity	To	356 stal Cost 250 stal Cost
After procuring all required permits, debris using dust control methods. If away daily using dump trailers. Portable Toilet Provide temporary toilet facilities fro	Remove dumpster and repair ar Bio m job start until approval of per Bio , celling mounted smoke and he utside of sleeping areas.	y evidence I Cost: manent faci I Cost: at detector	Base Base Base s permane	XXntly wir	Quantity GEN REQ Quantity GEN REQ ed into a rec	To	ul debris 356 tal Cost 250 tal Cost es with 750

Combination CO / Smoke Detector Hard Wired				GEN REQ	
Install a hard wired combination carbon monoxide and smoke	detector with ba	ittery back u	p.	•	
•	Bid Cost:		_x	=	250
,		Base		Quantity	Total Cost
Replace Drain Line Under Sink	•		•	KITCHEN	
Plumbing Code,					andards and the
ine between Michell sink and washing machine is not volke					600
	Bid Cost:		_x		Total Cost
A Commence of the Commence of		·		•	·
Celling Repair					
Repair ceiling finish. Patch drywall or plaster holes in ceiling of mesh with the appropriate material. Wet sand and smooth.	greater than one	inch. All oth	ers use	e an adhesive m	esh and mud over
	Bid Cost:		х	Ħ	150
		Base		Quantity	Total Cost
Cabinet Repair				 KITCHEN	·
	bottom, Finish v	vith white se	ml-glo	ss low-VOC pair	nt.
	Did Cook		Y	Ħ	175
	Bid Cost:	Base	^	Quantity	Total Cost
Online & Daniela	• • • • • • • • • • • • • • • • • • • •	•			
•	l doors and draw	/ers ,		REPORTER	•
	Pid Coats		x	=	175
	Bid Cost:	Base	^_	Quantity	Total Cost
					e john en
	x receptacle and	l cover plate	, Fish v		all tear out as needed.
moterial materials and materia		•			SoG
•	Bid Cost: _		x	=	
and the second	• •	Base		Quantity	Total Cost
		,			
		•			
	Replace the drain line and fittings from the sink basket to the Plumbing Code. * line between Kitchen sink and washing Machine is not vented. Ceiling Repair Repair ceiling finish. Patch drywall or plaster holes in ceiling a mesh with the appropriate material. Wet sand and smooth. Cabinet Repair Repair base cabinet under kitchen sink by installing plywood. Cabinet Repair Repair base cabinets with new hardware and pulls. Repair all Add Magnetic closures to all cabinet doors. GFCI Receptacle 20 AMP Install a flush mounted, ground fault circuit interrupted, dupled.	Replace the drain line and fittings from the sink basket to the horizontal brance Plumbing Code. * line between Kitchen sink and washing Machine is not vented properly. Replace the drain line and fittings from the sink basket to the horizontal brance Plumbing Code. * line between Kitchen sink and washing Machine is not vented properly. Replace the line of the sink base calling finish. Patch drywall or plaster holes in celling greater than one mesh with the appropriate material. Wet sand and smooth. Bid Cost:	Replace Drain Line Under Sink Replace the drain line and fittings from the sink basket to the horizontal branch drain line and Plumbing Code. * line between Kitchen sink and washing Machine is not vented properly. Repair to Code is Bid Cost: Bid Cost: Base Celling Repair Repair celling finish. Patch drywall or plaster holes in celling greater than one inch. All oth mesh with the appropriate material. Wet sand and smooth. Bid Cost: Base Cabinet Repair Repair base cabinet under kitchen sink by installing plywood bottom. Finish with white see Bid Cost: Base Cabinet Repair Repair base cabinets with new hardware and pulls. Repair all doors and drawers. Add Magnetic closures to all cabinet doors Bid Cost: Base GFCI Receptacle 20 AMP Install a flush mounted, ground fault circuit interrupted, duplex receptacle and cover plate. Bid Cost:	Replace Drain Line Under Sink Replace the drain line and fittings from the sink basket to the horizontal branch drain line per the Plumbing Code. * line between Kitchen sink and washing Machine is not vented properly. Repair to Code Require Bid Cost:	Replace Drain Line Under Sink Replace the drain line and fittings from the sink basket to the horizontal branch drain line per the Construction St Plumbing Code. * line between Kitchen sink and washing Machine is not vented properly. Repair to Code Requirements * Bid Cost:

10				
12.	Range	Hood	Exterior	Vented

KITCHEN

Install an exterior ducted enameled range hood with integral controls and light capable of 100 cfm at 70 sones. Attach hood to cabinet with screws, Include metal vent and roof or wall cap/damper assembly, using #14 copper Romex. Owner's choice of color.



Bid Cost: X = 750

(C. Resilient Flooring

KITCHEN

Install 25 year warrantied resilient floor covering per manufacturer's specifications. Include transitions and painted or stained wood quarter-round at all perimeters to complete installation.



Bid Cost: X = 1350

Base Quantity Total Cost

17. Floor System Repair

BATHROOM - MAIN

Remove all fixtures not built in. Dispose of damaged/unsafe components of floor assembly. Work may include installation of 2"x 10" joists hung 16" on center, plywood or tongue and groove subfloor, include replacing all deteriorated band joists and insulating floor to code.



Bid Cost: X = SOO

Base Quantity Total Cost

18. Resilient Flooring

BATHROOM - MAIN

Install 25 year warrantied resilient floor covering per manufacturer's specifications. Include transitions and painted or stained wood quarter-round at all perimeters to complete installation.



Bid Cost: X = 350

Base Quantity Total Cost

9.	Bath Exhaust Fan Replace						
	Install a ceiling or through-the-wall, exterior ducted, vent fan v Repair any tear out.	with damper, Inc	lude power	and sv	vitch wiring usir	ng #14 copp	er Romex.
		Bid Cost:		х	=	ı	500
			Base '		Quantity	Tota	al Cost
	100 - 100 -						
١,	GFCI Receptacle 20 AMP				BATHROO	M - MAIN	
	Install a flush mounted, ground fault circuit interrupted, dupled	x receptacle and	cover plate	. Fish	wire and repair	all tear out	as needed
		Bid Cost:		x	m		350
		Did 0031,	Base	^`	Quantity	Tota	l Cost
	Ceramic Wall Tile- Bathtub Surround						
	grout and apply mildew resistant white silicone caulk at all se	arriol invidio liba	and hihe he	, ional	J.101		
		Bid Cost:		_x_			1200
		Bid Cost:	Base	_x_	= Quantity	Tota	1200 al Cost
2	Grab Bars	Bid Cost:		x	Quantity 	Tota	
2 4	Grab Bars Install 1 1/2" diameter S/S Grab Bars on 3 walls at height of 3 Owners choice of locations.		Base	XX n wall.			il Cost
) ~ ^	Install 1 1/2" diameter S/S Grab Bars on 3 walls at height of 3	6" (include wood	Base d blocking li		Each bar must		ounds).
· A	Install 1 1/2" diameter S/S Grab Bars on 3 walls at height of 3		Base d blocking li		Each bar must	hold 300 pc	ounds).
	Install 1 1/2" diameter S/S Grab Bars on 3 walls at height of 3 Owners choice of locations.	6" (include wood	Base d blocking li		Each bar must	hold 300 pc	ul Cost bunds).
	Install 1 1/2" diameter S/S Grab Bars on 3 walls at height of 3	6" (include wood Bid Cost:	Base d blocking li Base	_X	Each bar must Quantity	hold 300 pc	ounds). 225
	Install 1 1/2" diameter S/S Grab Bars on 3 walls at height of 3 Owners choice of locations. Insulate Floor R-19 Install R-19 Kraft faced batt fiberglass insulation to floor where	6" (include wood Bid Cost:	Base d blocking li Base	_X	Each bar must Quantity	hold 300 pc	ounds). 225 al Cost g wire, "tige
	Install 1 1/2" diameter S/S Grab Bars on 3 walls at height of 3 Owners choice of locations. Insulate Floor R-19 Install R-19 Kraft faced batt fiberglass insulation to floor where	6" (include wood Bid Cost:	Base d blocking in Base from the second seco	_X	Each bar must Quantity	hold 300 pc	ounds). 225 al Cost g wire, "tige
	Install 1 1/2" diameter S/S Grab Bars on 3 walls at height of 3 Owners choice of locations. Insulate Floor R-19 Install R-19 Kraft faced batt fiberglass insulation to floor where	6" (include wood Bid Cost: 	Base d blocking li Base	X_st face	Each bar must Quantity	Tota Use strong	ounds). 229 Il Cost Uniferential Cost Cost
•	Install 1 1/2" diameter S/S Grab Bars on 3 walls at height of 3 Owners choice of locations. Insulate Floor R-19 Install R-19 Kraft faced batt fiberglass insulation to floor where	6" (include wood Bid Cost: 	Base d blocking in Base from the second seco	X_st face	Each bar must Quantity heated space.	Tota Use strong	ounds). 225 Il Cost Uniferential Cost Cost
	Install 1 1/2" diameter S/S Grab Bars on 3 walls at height of 3 Owners choice of locations. Insulate Floor R-19 Install R-19 Kraft faced batt fiberglass Insulation to floor where teeth" or mesh to hold insulation in place.	6" (include wood Bid Cost:	Base d blocking in Base r barrier mu	X sst face	Each bar must Quantity heated space.	Tota Use strong	ounds). 229 al Cost wire, "tige (OOC
•	Install 1 1/2" diameter S/S Grab Bars on 3 walls at height of 3 Owners choice of locations. Insulate Floor R-19 Install R-19 Kraft faced batt fiberglass insulation to floor where teeth" or mesh to hold insulation in place. Attic Insulation Increase to R-38 Increase attic insulation to R-38, contractor to attach verification.	6" (include wood Bid Cost: e missing. Vapo Bid Cost: on to rafter at at	Base Base Base Base Base	X sst face	Each bar must Quantity heated space.	Tota Use strong	ounds). 229 al Cost wire, "tige (OOC
•	Install 1 1/2" diameter S/S Grab Bars on 3 walls at height of 3 Owners choice of locations. Insulate Floor R-19 Install R-19 Kraft faced batt fiberglass insulation to floor where teeth" or mesh to hold insulation in place. Attic Insulation Increase to R-38 Increase attic insulation to R-38, contractor to attach verification.	6" (include wood Bid Cost:	Base Base Base Base Base	X sst face	Each bar must Quantity heated space. Quantity seen. Include ve	Tota Use strong	ounds). 229 Il Cost Il Cost Il Cost Il Cost Il Cost
3.	Install 1 1/2" diameter S/S Grab Bars on 3 walls at height of 3 Owners choice of locations. Insulate Floor R-19 Install R-19 Kraft faced batt fiberglass insulation to floor where teeth" or mesh to hold insulation in place. Attic Insulation Increase to R-38 Increase attic insulation to R-38, contractor to attach verification.	6" (include wood Bid Cost: e missing. Vapo Bid Cost: on to rafter at at	Base Base r barrier mu Base	X x	Each bar must Quantity heated space.	Tota Use strong	al Cost 229 al Cost U OOC al Cost

		Bid Cost:	. >	(=	700
			Base	Quantity		Cost
. ,	Aluminum Storm Door					•
١	Install an aluminum combination storm and screen door. Co * Front and Rear .	omplete with self c	oser and lockl	ng hardware.		
		Bid Cost:)	ζ	=	650
			Base	Quantity	Total	Cost
	Prehung Metal Door Entrance Remove existing door, frame and threshold, Install new En					
1	dead bolt and lever handled door hardware keyed alike. Ins Apply primer and topcoat. This installation to include repair floor joists and sill. REAR Door.	ing any damaged h	neader, door fr	aming, to include	ng will match ex e wall framing, s	lsting. ub-floor, てひの
		Bid Cost:		Χ		
			Raco	Quantity	Total	Chet
			Base	Quantity	Total	Cost
1	Vinyl Window Dispose of window units and any security bars. Field meas windows including half screens. Insulate rough opening. In:	stall new extensior	all new Energy i jambs, casing	/ Star rated vinyl g and sill as need	, double glazed led, prime and p	LOW- E
) (Vinyl Window Dispose of window units and any security bars, Field meas	stall new extenslor s needed, Repair a ming (to include ki	all new Energy jambs, casing ill areas distur ng studs, jack	/ Star rated vinyl g and sill as need bed by removal a	, double glazed ded, prime and p and installation.	LOW- E paint. This
1	Vinyl Window Dispose of window units and any security bars. Field meas windows including half screens. Insulate rough opening. In: Exterior trim to be wrapped in PVC coated aluminum coil a installation is to include repairing any damaged header, fra	stall new extensior s needed, Repair a ming (to include ki nave tempered glas	all new Energy i jambs, casing ill areas disturi ng studs, jack ss.	/ Star rated vinyl g and sill as need bed by removal a studs etc.) sub-fl	, double glazed ded, prime and p and installation. loor, floor joists,	LOW- E paint. This
1	Vinyl Window Dispose of window units and any security bars. Field meas windows including half screens. Insulate rough opening. In: Exterior trim to be wrapped in PVC coated aluminum coil a installation is to include repairing any damaged header, fra	stall new extensior s needed, Repair a ming (to include ki nave tempered glas	all new Energy i jambs, casing ill areas disturi ng studs, jack ss.	/ Star rated vinyl g and sill as need bed by removal a	, double glazed ded, prime and p and installation. loor, floor joists,	LOW- E paint. This band
) 	Vinyl Window Dispose of window units and any security bars. Field meas windows including half screens. Insulate rough opening. In: Exterior trim to be wrapped in PVC coated aluminum coil a installation is to include repairing any damaged header, fra joists and sill. Any windows replaced in a bathroom must he	stall new extensior s needed, Repair a ming (to include ki nave tempered glas	all new Energy i jambs, casing ill areas disturi ng studs, jack iss.	y Star rated vinyl g and sill as need bed by removal a studs etc.) sub-fl X	, double glazed ded, prime and p and installation. loor, floor joists,	LOW- E paint. This band
) 	Vinyl Window Dispose of window units and any security bars. Field meas windows including half screens. Insulate rough opening. In: Exterior trim to be wrapped in PVC coated aluminum coil a installation is to include repairing any damaged header, fra joists and sill. Any windows replaced in a bathroom must head to the screen was to be supported by the screen was a	stall new extensions needed, Repair a ming (to include killave tempered glas	all new Energy I jambs, casing Ill areas disturi ng studs, jack es. Base	y Star rated vinyl g and sill as need bed by removal a studs etc.) sub-fl X Quantity	, double glazed ded, prime and p and installation. loor, floor joists,	LOW- E paint. This band Current Cost
) 	Vinyl Window Dispose of window units and any security bars. Field meas windows including half screens. Insulate rough opening. In: Exterior trim to be wrapped in PVC coated aluminum coil a installation is to include repairing any damaged header, fra joists and sill. Any windows replaced in a bathroom must he	stall new extensions needed, Repair a ming (to include killave tempered glas	all new Energy I jambs, casing Ill areas disturi ng studs, jack es. Base	y Star rated vinyl g and sill as need bed by removal a studs etc.) sub-fl X Quantity	, double glazed ded, prime and p and installation. loor, floor joists,	LOW- E paint. This band CLOC Cost
) 	Vinyl Window Dispose of window units and any security bars. Field meas windows including half screens. Insulate rough opening. In: Exterior trim to be wrapped in PVC coated aluminum coil a installation is to include repairing any damaged header, fra joists and sill. Any windows replaced in a bathroom must head to the screen was to be supported by the screen was a	stall new extensions needed, Repair a ming (to include kinave tempered glasses Bid Cost:	all new Energy jambs, casing il areas disturi ng studs, jack ss. Base	y Star rated vinyl g and sill as need bed by removal a studs etc.) sub-fl X Quantity	, double glazed ded, prime and p and installation. loor, floor joists,	LOW- E paint. This band CLOC Cost
) 	Vinyl Window Dispose of window units and any security bars. Field meas windows including half screens. Insulate rough opening. In: Exterior trim to be wrapped in PVC coated aluminum coil a installation is to include repairing any damaged header, fra joists and sill. Any windows replaced in a bathroom must head to the screen was to be supported by the screen was a	stall new extensions needed, Repair a ming (to include kinave tempered glasses Bid Cost:	all new Energy jambs, casing il areas disturi ng studs, jack es. Base	y Star rated vinyl g and sill as need bed by removal a studs etc.) sub-fi X Quantity n at main sewer	, double glazed ded, prime and pand installation. loor, floor joists, Total	LOW- E paint. This band 6400 Cost
) 	Vinyl Window Dispose of window units and any security bars. Field meas windows including half screens. Insulate rough opening. In: Exterior trim to be wrapped in PVC coated aluminum coil a installation is to include repairing any damaged header, fra joists and sill. Any windows replaced in a bathroom must head to the screen was to be supported by the screen was a	stall new extensions needed, Repair a ming (to include kinave tempered glasses Bid Cost:	all new Energy I jambs, casing Ill areas disturing studs, jack Iss. Base e to connection	y Star rated vinyl y and sill as need bed by removal a studs etc.) sub-fl X Quantity n at main sewer	, double glazed ded, prime and pand installation. loor, floor joists, Total	LOW- E paint. This band 6400 Cost
	Vinyl Window Dispose of window units and any security bars. Field meas windows including half screens. Insulate rough opening. In: Exterior trim to be wrapped in PVC coated aluminum coil a installation is to include repairing any damaged header, fra joists and sill. Any windows replaced in a bathroom must have been secured. Snake Waste Lines Power-snake all bath and kitchen drain lines to clear any bases.	stall new extensions needed, Repair a ming (to include kinave tempered glasseve temp	all new Energy I jambs, casing Ill areas disturing studs, jack Iss. Base e to connection Base	y Star rated vinyl g and sill as need bed by removal a studs etc.) sub-fi X Quantity n at main sewer X Quantity service one 3-pic	, double glazed ded, prime and pand installation. loor, floor joists, Total service at the serv	LOW- E paint. This band Cost reet. 350 Cost
	Vinyl Window Dispose of window units and any security bars. Field meas windows including half screens. Insulate rough opening. In: Exterior trim to be wrapped in PVC coated aluminum coil a: Installation is to include repairing any damaged header, fra joists and sill. Any windows replaced in a bathroom must have been smaller to clear any bit of the properties of the pro	stall new extensions needed, Repair a ming (to include kinave tempered glasseve temp	all new Energy I jambs, casing Il areas disturing studs, jack iss. Base e to connection Base ule 40 PVC to a main clean of	y Star rated vinyl g and sill as need bed by removal a studs etc.) sub-fi X Quantity n at main sewer X Quantity service one 3-pic	, double glazed ded, prime and pand installation. loor, floor joists, Total service at the si Total ece bath,kitcher de	LOW- E paint. This band Cup Cost reet. Cost Cost
	Vinyl Window Dispose of window units and any security bars. Field meas windows including half screens. Insulate rough opening. In: Exterior trim to be wrapped in PVC coated aluminum coil a: Installation is to include repairing any damaged header, fra joists and sill. Any windows replaced in a bathroom must have been smaller to clear any bit of the properties of the pro	stall new extensions needed, Repair a ming (to include kinave tempered glasses Bid Cost:	all new Energy I jambs, casing Il areas disturing studs, jack iss. Base e to connection Base ule 40 PVC to a main clean of	y Star rated vinyl y and sill as need bed by removal a studs etc.) sub-fi X Quantity n at main sewer X Quantity service one 3-pic out outside to con	, double glazed ded, prime and pand installation. loor, floor joists, Total service at the si Total ece bath,kitcher de	LOW- E paint. This band CGSt Cost Cost and 2750

· Work Specification - City of Charlotte Housing & Neighborhood Services

31. Electric Service 200 AMP

Replace electrical service with new 200 amp, main disconnect, 110/220 volt, 24 circuit panel board, meter socket, weather head, service cable, ground rods and cable. Include replacement of all sub-panels. Caulk exterior service penetration. * Terminate all old Fuse Boxes and Equipment in Laundry Room.

	Bld Cost:		Х		Ħ	2800
		Base		Quantity		Total Cost
2 . Cabinet Repair		•		Bedroom	ı#2	
Repair cabinet door at top of closet. * Owner has door- Hin	ge broken off. Repl	lace hinges	and In	stall .	:	
	Bid Cost:		X		:	50
	Did Cost:	Base	_^_	Quantity		Total Cost
3. Refrigerator18 CF Frost Free			٠.,	Kitchen -	- Health	v Homes
Dispose of old refrigerator. Install a 2 door, Energy Star rate match existing refrigerator like for like (i.e. volume, style (to refrigerator with ice maker as well).				18 cubic fee	t. New	refrigerator is to
	Bld Cost:	1	Х		=	900
		Base		Quantity		Total Cost
կ, Electric Stove Top and Self Cleaning Oven	4	. •		Kitchen-	Healthy	y Homes
Dispose of existing oven. Install a 30" electric, self cleaning oven is to be Energy Star rated and have a smooth cooktop						
Owner choice of black or white.	Bid Cost:		х		=	750
Owner choice of black or white,	Bid Cost:	Base	_x	Quantity		750 Total Cost
Owner choice of black or white,	Bid Cost:		_x			•
	roof deck (include	Base 96 sq.ft, of	deckin	Quantity Exterior g replaceme		Total Cost
Tear Off & Reroof Shingles Remove and dispose of existing roofing, inspect and repair 30 year architectural shingles, include ice and water shield	roof deck (include at all roof edges, fo	Base 96 sq.ft. of elt paper, sh	deckin	Quantity Exterior g replaceme		Total Cost
Tear Off & Reroof Shingles Remove and dispose of existing roofing, inspect and repair 30 year architectural shingles, include ice and water shield	roof deck (include	Base 96 sq.ft. of elt paper, sh	deckin	Quantity Exterior g replaceme		Total Cost d) and install new ts, flashing and all
Tear Off & Reroof Shingles Remove and dispose of existing roofing, inspect and repair 30 year architectural shingles, include ice and water shield	roof deck (include at all roof edges, fo	Base 96 sq.ft. of elt paper, sh	deckin	Quantity Exterior g replaceme over ridge ve		Total Cost d) and install new ts, flashing and all
Tear Off & Reroof Shingles Remove and dispose of existing roofing, inspect and repair 30 year architectural shingles. Include ice and water shield necessary accessories.	roof deck (include at all roof edges, fe Bid Cost:	Base 96 sq.ft. of elt paper, sh	deckin	Quantity Exterior g replaceme over ridge ve	ent, boo	Total Cost d) and install new ts, flashing and all